

2024-04-04, v7.0.5.502

1. #35662 Communicate with BT Pairing using a file extra parameter.

2023-12-13, v7.0.5.501

1. #32215 Fix Zebra problem with AccessibilityService.

2023-11-27, v7.0.5.500

- 1. #31843 Volume Buttons not working on Zebra devices
- 2. New MinSdk version 23 (Marshmallow)

2023-06-23, v7.0.4.527

1. #28488 AccessibilityService cause External Keyboard error.

2023-03-10, v7.0.4.526

1. #25151 ScannerType 4 delay on some devices.

2022-08-25, v7.0.4.525

1. #20466 Unpairing barcode text not displayed.

2022-05-23, v7.0.4.524

1. #18071 MC93 keyboard stopped working after update of firmware

2022-05-10, v7.0.4.523

1. #17644 Scanner non disponible

2022-05-04, v7.0.4.522

1. #17513 Intermarche has problems with Printer Reconnect

2022-04-09, v7.0.4.521

1. #16781 Special treatment for LMS application.

2022-04-06, v7.0.4.520

1. #16455 Bluetooth printing

2022-03-14, v7.0.4.519

- 1. #15959 Add control for CT45P. closeProxy failor on this device.
- 2. Updated Gradle Tools from 7.0.2 to 7.0.4



2022-02-25, v7.0.4.518

- 1. #15364 BtPairing crash if /sdcard/ bt mac.txt file is not present
- 2. #14298 The Proglove ring is not taken into account in the event of a connection retry

2022-02-10, v7.0.4.517

- 1. #14979 Symbology ITF for ProGlove Scanner unknown
- 2. Updated Gradle Tools from 4.1.3 to 7.0.2
- 3. Updated Kotlin from 1.4.32 to 1.5.31

2021-07-21, v7.0.4.516

- 1. #1186 Scanner NFC pairing (ScannerType 110) (improvements)
- 2. Implemented HubOne JSON Library

2021-06-10, v7.0.4.515

1. #1761 Add new ViaIntent solution for Unitech Intent Scanner

2021-04-21, v7.0.4.514

- 1. #1742 HubOne Connection Manager (changed back certificate to TellNext)
- 2. Gradle updated from 4.1.1 to 4.1.3
- 3. Kotlin updated from 1.4.21 to 1.4.32

2021-02-02, v7.0.4.513

- 1. #1669 Pop-up pairing not validate despite activity is on
- 2. Gradle updated from 4.0.2 to 4.1.1

2020-12-15, v7.0.4.512

- 1. #1687 Turn ON/OFF NFC on Datalogic devices
- 2. #1678 BT MAC is read on Zebra devices if correct version of OEMInfo is installed, 9.0.0.282+

2020-11-26, v7.0.4.511

- 1. #1676 RS507 pairing error on second launch
- 2. #1682 Could not connect to Pro Glove with new version of Insight 1.0.18

2020-11-25, v7.0.4.510

1. #1163 - Send a beep to the rings in the event of an error beep. (fix for ScannerType 111 that did not always beep)



2020-11-13, v7.0.4.509

1. #1163 - Send a beep to the rings in the event of an error beep.

2020-11-05, v7.0.4.508

1. #1587 - Scanner icon status change

2020-09-14, v7.0.4.507

- #770 Adapt BtPairing to new API 29 (Android 10) about app launch (partially done)
- 2. #1588 Add unpairing barcode for Zebra RS5100 scanner

2020-05-15, v7.0.4.506

1. Implemented FollowMe # in log for ScannerType 4, 6 and HeadsetActivity

2020-03-31, v7.0.4.505

- 1. #994 NFC headset problems, new mode: MODE NATIVE
- 2. #1421 Added stop button for Headset Type 1
- 3. #1428 Improve design on some screen variants (tablets and landscape)
- 4. #1287 Sur les casques BT, modifier la gestion du BT.SCO (HFP profile)

2020-02-28, v7.0.4.504

- 1. #1186 Accept scanner pairing using NFC
- 2. #1186 ScannerType 110 implemented

2020-02-21, v7.0.4.503

1. #1271 New Scanner Type 111 for Zebra Scanners (part #1)

2020-02-03, v7.0.4.502

1. #1267 Automatic Pairing Request click on Samsung devices

2020-01-31, v7.0.4.501

- 1. #1266 Zebra scanner LI4278 does not connect...
- 2. #1268 Problems printing with ZD420 printer in USB mode (new Timeout parameter)

2020-01-20, v7.0.4.500

1. #1181 Allow auto connect to PRINTER with new autoConnectMAC option

2019-12-19, v7.0.3.567

1. #1128 Problèmes appairage Honeywell Xenon 1902 sur ET51



2019-12-05, v7.0.3.566

1. #1129 Add more information for responses from Printer services and create documentation

2019-12-04, v7.0.3.565

1. #1119 Add new Parameter "BTOnAtOpen" and create HOWTO document

2019-12-02, v7.0.3.564

1. #965 Implemented old Intent communication for Auchan

2019-11-26, v7.0.3.563

1. #965 Check if ProGlove already active when used through TellNext

2019-11-20, v7.0.3.562

1. #965 Intégration de la bague PROGLOV MARK II dans nos solutions

2019-11-12, v7.0.3.561

1. #1083 BT printer disconnected by scanner service

2019-10-26, v7.0.3.559

- 1. #1024 Print by USB
- 2. Adaption of views to Tablet for nicer user interface

2019-10-13, v7.0.3.558

1. #1023 Print by Bluetooth

2019-10-08, v7.0.3.557

1. #1003 MAC file missing

2019-09-27, v7.0.3.556

- 1. #999 WD100 bug, Wrong MAC given from the OS
- 2. #1000 Camera button when pairing headset

2019-09-16, v7.0.3.555

1. #971 NullPointerException found in BT Pairing (kept occurring after last fix)

2019-09-13, v7.0.3.554

1. #971 NullPointerException found in BT Pairing



2019-09-10, v7.0.3.553

1. #854 Create a text file with detailed version when launching

2019-09-02, v7.0.3.552

1. Bug fix, when receiving a headset unpair request from another APP, it was not always unpaired.

2019-08-08, v7.0.3.551

- 1. New scanner type 7 (combo between 2 and 6)
- 2. Fixed bug, was showing device MAC as 02:00:00:00:00:00
- 3. Version was not always displayed correctly
- 4. Added silentMode

2019-07-19, v7.0.3.550

- 1. Minor fix for HIDActivity
- 2. Fixed reconnect to Honeywell 8670 scanner when connection was lost (timeout, battery change, etc...)
- 3. Logcat function introduced

2019-06-11, v7.0.3.549

- 1. Updated messages for ScannerType 6. Calling APPs will now be able to know when connection to scanner was connected, disconnected and lost.
- 2. Made unpairing barcode bigger for Unitech WD100 devices.

2019-05-03, v7.0.3.548

1. NFC Pairing with headset shows a Dialog where the user has to press yes. Dialog is now treated automagically from the AccessibilityService.

2019-04-04, v7.0.3.547

- 1. IntentScanner DataLogic fix, Added options "HasCategory" and "Category"
- 2. Updated and improved ScannerType 6

2019-02-28, v7.0.3.546

- 1. Changed Unpair barcode to be available for all ScannerTypes. This barcode will not activate Bluetooth.
- 2. Honeywell Barcode type works with all scanner types
- 3. When exiting BT Pairing when the Unpair barcode was displayed, TellNext did not receive the No Device Connected message
- 4. The Unpair barcode occupied full screen on Unitech WD100



2019-02-05, v7.0.3.545

1. NEW: Honeywell UnPair barcode added.

2019-01-14, v7.0.3.544

1. NEW: New option, ShowUnpairBarcode. When set to true and an unpair barcode will be shown before the pairing is possible.

Only implemented for BarcodeType FNC3 (Zebra) and Scanner Types: 0, 1, 2, 4 and 6. (works with Tellnext v1.0.8.501+)

2018-12-21, v7.0.3.543

- 1. "ScannerType" 6. Fixed to be even more stable. Works best with PRE Oreo 8.1. Oreo 8.1 and POST version works but auto connect of scanner does not when connection was lost, sometimes you have to scan several times to connect the scanner.
- 2. Improved "ScannerType" 5 for use of UBS (Unitech Bluetooth Service) to connect the MS652 scanners.

2018-12-13, v7.0.3.542

- 1. NEW: "ScannerType" 6. The most stable option to connect a Zebra RS507 on most devices.
- 2. NEW: Added an Accessibility Service, when active, the Pairing Request dialog will be closed automagically
- 3. Removed the "Timeout" option. It will now be ignored, no matter what "ScannerType" being used
- 4. The Pairing Request Dialog should always be displayed in front of the current application when using "ScannerType" 6

2018-12-07, v7.0.3.541

Added HeadsetType option

2018-11-29, v7.0.3.540

1. Read "bt_mac.txt" from /sdcard if Bluetooth MAC address could not be retrieved programmatically. Implemented for Android v8.1+ (Oreo and above).

2018-11-22, v7.0.3.537-539

- 1. Fixes for Alinéa (ID-Logistics)
- 2. Added ScannerType 5 for use of Unitech Bluetooth Service. Internal use only!



2018-11-12, v7.0.3.536

1. Added message used when communicating with SpeakerNext.

2018-11-09, v7.0.3.535

- 1. NEW: Complete re-write of the connecting part to headsets. Both for NFC and in discovery mode
- 2. Added new events (scanner connected) needed by SpeakerNext
- 3. Fixes for Unitech scanner MS652

2018-10-11, v7.0.3.534

- 1. NEW: Added scanner type option Generic SPP (value 4) to connect any SPP scanner.
- 2. Fixed Honeywell option, it now works perfectly with the Granit 1981i scanner on any device.

2018-10-03, v7.0.3.533

- 1. NEW: Added HID option to connect scanners in HID mode.
- 2. NEW: Added "HONEYWELL" option as "BarcodeType" to connect automagically Honeywell devices as Master SPP.

This does NOT work so it must be disabled in the profile.jcf at the moment.

- 3. FIX: Budgie made BT Pairing crash on connect.
- 4. FIX: Connecting with the MS652 scanner the APP sometimes got in a infinity busy loop and would take all CPU from the device Issue: #147 Pairing with MS652