

2022-01-21, v3.0.4.500

1. #14023 Create a unified version of BarScannerZebra and BarScanner Honeywell

2021-06-22, Honeywell, v3.0.3.624

- 1. #1762 When scanning MAC in SDK mode, not recognized for headset
- 2. Gradle update from 4.1.1 to 4.1.3

2021-06-22, Zebra, v3.0.3.533

1. #1762 When scanning MAC in SDK mode, not recognized for headset

2021-06-04, Google Play, v3.0.3.708

- 1. #764 Scanner Camera a recompiler Android 10 (API 29)
- 2. #1760 BarScanner Camera not working on Android 9+
- 3. Gradle update from 4.1.1 to 4.1.3

2021-06-04, Zebra, v3.0.3.532

- 1. #1752 Paths in profile file
- 2. Gradle update from 4.1.1 to 4.1.3

2021-03-30, Zebra, v3.0.3.531

1. #1726 Zebra SDK - Using a virtual key to trigger a scan blocks the use of physical scan keys

2021-02-04, Zebra, v3.0.3.530

1. #1711 IdleTime not working with Zebra SSI scanners.

2021-02-02, Honeywell, v3.0.3.623

1. Minor update to make Zebra Pluggable scanner to work with Honeywell SDK

2021-01-13, Honeywell, v3.0.3.622

1. #1696 Add support for Honeywell BT scanner (Granit 1911i).

2020-11-26, Zebra, v3.0.3.529

1. Fixed problem with barcode being sent twice at every scan.

2020-11-13, Zebra, v3.0.3.528

1. #1163 Send a beep to the rings in the event of an error beep.



2020-11-13, Honeywell, v3.0.3.621

1. #1163 Send a beep to the rings in the event of an error beep. (NOT supported by Honeywell, but code adjusted for the future)

2020-11-05, Zebra, v3.0.3.527

1. #1587 Scanner icon status change

2020-11-05, Honeywell, v3.0.3.620

1. #1587 Scanner icon status change

2020-06-17, Zebra, v3.0.3.526

1. #1521 Le mode PickList ne fonctionne pas sur la RS5100 en mode SSI (added "PickListType": SOFTWARE, HARDWARE)

2020-02-26, Honeywell, v3.0.3.618

1. Colombia fix - "connect" message not sent when TellNext crashed

2019-12-19, Honeywell, v3.0.3.617

1. #1136 Communicate with Barscanner via json and write documentation

2019-12-18, Zebra, v3.0.3.525

1. #1136 Communicate with Barscanner via json and write documentation

2019-11-21, Zebra, v3.0.3.524

1. #1141 New version did not work well with Auchan APP

2019-11-15, Zebra, v3.0.3.523

1. #1097 Code 39 not working correctly on Zebra Scanners

2019-11-08, Zebra, v3.0.3.522

1. #1087 PickList not available on some devices created an anomaly in the settings configuration. Fail safe added.

2019-10-26, Honeywell, v3.0.3.616

1. Updated communication with TellNext

2019-10-26, Zebra, v3.0.3.521

1. Updated communication with TellNext



2019-10-24, Honeywell, v3.0.3.615

- 1. Redmine #1067 Honeywell Barscanner CODE39 Some codes does not work
- 2. Changed the Honeywell .jar library to the .aar release

2019-10-24, Zebra, v3.0.3.520

1. Redmine #1068 - SSI Zebra APP overlapped by BT Pairing

2019-09-23, Camera-Google Play, v3.0.3.614

- 1. Fixed compilation error
- 2. Implemented silentMode
- 3. Implemented logcat version
- 4. Redmine #854 Create a text file with detailed version when launching

2019-09-23, Camera-Zbar, v3.0.3.614

- 1. Fixed compilation error
- 2. Implemented silentMode
- 3. Implemented logcat version
- 4. Redmine #854 Create a text file with detailed version when launching

2019-09-23, Honeywell, v3.0.3.614

1. Change silentMode to be homogeneous

2019-09-23, Zebra, v3.0.3.520

1. Change silentMode to be homogeneous

2019-09-12, Honeywell, v3.0.3.613

1. Redmine #854 - Create a text file with detailed version when launching

2019-09-12, Zebra, v3.0.3.519

1. Redmine #854 - Create a text file with detailed version when launching

2019-08-13, Honeywell, v3.0.3.612

silentMode implmented

2019-08-13, Zebra, v3.0.3.518

silentMode implmented

2019-07-22, Honeywell, v3.0.3.611

1. Logcat function introduced



2019-07-22, Zebra, v3.0.3.517

1. Logcat function introduced

2019-06-06, Honeywell, v3.0.3.610

1. When Sending ACTIVATE/DEACTIVATE the app now responds (used by SpeakerNext v2.1.2.500+)

2019-06-06, Zebra, v3.0.3.516

- 1. When Sending ACTIVATE/DEACTIVATE the app now responds (used by SpeakerNext v2.1.2.500+)
- 2. Changed behaviour for sending connect status to other apps (only SpeakerNext affected)

2019-02-29, Honeywell, v3.0.3.608 1. Implemented support for double scanners when using the internal scanner together with SpeakerNext and BT Pairing 2. Changed service to be in the foreground (was shut down by the OS)

2019-03-15, Zebra, v3.0.3.515

- 1. Fix status Intent sent to TellNext when scanner is connected.
- 2. Updated target SDK to 26

2019-02-29, Honeywell, v3.0.3.608

- 1. Implemented support for double scanners when using the internal scanner together with SpeakerNext and BT Pairing
- 2. Changed service to be in the foreground (was shut down by the OS)

2019-02-29, Zebra, v3.0.3.514

- 1. Implemented support for double scanners when using the internal scanner together with SpeakerNext and BT Pairing
- 2. Changed service to be in the foreground (was shut down by the OS)
- 3. Fixed bug, if "Symbologies" part was missing in json, the APP crashed.

2019-01-31, Zebra, v3.0.3.513

1. Implemented SCANNER_SOFT_TRIGGER (ScanByClick) (TellNext minimum version v1.0.8.501)

2018-11-30, Zebra, v3.0.3.512

1. Added and fixed ExtraOptions for UPC A, I25 and D25



2018-11-30, Honeywell, v3.0.3.607

1. Added and fixed ExtraOptions for UPC A, I25 and D25

2018-11-27, Zebra, v3.0.3.511

- 1. Added new return values used when communicating with SpeakerNext
- 2. Added version number when showing welcome dialog (Issue: #161)

2018-11-12, Honeywell, v3.0.3.606

1. Added new return values used when communicating with SpeakerNext

2018-10-16, Zebra, v3.0.3.510

1. Fix: RS6000 SSI mode Issue: #160 RS6000 scanner light doesn't turn on

2018-10-01, Honeywell, v3.0.3.605

1. NEW: Added information message when clicking the APP icon, Issue: #148 Running APK nothing displayed