

Latest recommended config:

_tnx_profile.jcf

```
"BluetoothSPP": {
  "On": true,
  "Filter": "",
  "PIN": "",
  "UseDeviceMajor": false,
  "UnpairAll": false,
  "DiscoveryOn": false,
  "BarcodeType": "FNC3",
  "ShowUnpairBarcode": false,
  "ScannerType": 6,
  "TerminatorWait": 0,
  "Terminators": ""
},
```

Tested successfully on:

| Android Oreo (8.x) | | | | | |
|--------------------|--------|-----------------|------|-------------|--------------------|
| Manufacturer | Device | Android Version | Date | Tnx version | Recommended Config |
| | Notes | | | | |
| | | | | | |
| | | | | | |

| Android Nougat (7.x) - No more tested on this version | | | | | |
|---|--|-----------------|----------|--|--------------------------|
| Manufacturer | Device | Android Version | Date | Tnx version | Config deviation / Notes |
| M3 mobile | M3SM15N | 7.1.1 | 02/04/19 | Emulator 1.0.9.508 BT Pairing 7.0.3.546 | "ScannerType": 6, |
| | <ul style="list-style-type: none"> - Sometimes it is necessary reading the pairing barcode twice. - Headset pairing request requires the user interaction. - When the scanner LEDs remain blinking and it is impossible to re-pair, it is required to remove and reinsert the battery from the scanner. | | | | |

