Hub One

Latest recommended config:

_tnx_profile.jcf

```
"BluetoothSPP": {
  "On": true,
  "Filter": "RS507",
  "PIN": "",
  "UseDeviceMajor": false,
  "UnpairAll": false,
  "DiscoveryOn": false,
  "BarcodeType": "FNC3",
  "ShowUnpairBarcode": false,
  "ScannerType": 6,
  "TerminatorWait": 0,
  "Terminators": ""
},
```

Tested successfully on:

Manufacturer	Device	Android Version	Date	Tnx version	Recommended Config
	Notes				
Honeywell	CT60	8.1.0	19/07/19	Emulator 1.0.11.512 BT Pairing 7.0.3.548	`"UnpairAll": false, "ScannerType": 6,`
	• The test is old, we recommend using Scanner Type 111 (not tested) • Build number 86.00.10 not pairing SPP mode • 86.00.02 / 86.00.07 / 86.00.11 works well				

Android Oreo (8.x)

Manufacturer	Device	Android Version	Date	Tnx version	Config deviation / Notes

Android Nougat (7.x) – No more tested on this version

Recommendations:

- Some devices are not available for testing, despite this, we recommend the use of Scanner Type 111
- Use the Filter parameter as much as you can. It will be easier to establish the connection between devices.