# Hub One

Latest recommended config:

_tnx_profile.jcf

```
"BluetoothSPP": {
  "On": true,
  "Filter": "RS507",
  "PIN": "",
  "UseDeviceMajor": false,
  "UnpairAll": false,
  "DiscoveryOn": false,
  "BarcodeType": "FNC3",
  "ShowUnpairBarcode": false,
  "ScannerType": 6,
  "TerminatorWait": 0,
  "Terminators": ""
},
```

# Tested successfully on:

| Android Oreo (8.x) | | | | | |
|---|---|---|---|---|---|
| Manufacturer | Device | Android Version | Date | Tnx version | Recommended Config |
| | Notes | | | | |
| | | | | | |
| | | | | | |

| Android Nougat (7.x) – No more tested on this version | | | | | |
|---|---|---|---|---|---|
| Manufacturer | Device | Android Version | Date | Tnx version | Config deviation / Notes |
| Honeywell | EDA60K | 7.1.1 | 20/12/18 | Emulator 1.0.7.518 BT Pairing 7.0.3.543 | `"ScannerType": 6,` |
| | – The test is old, we recommend using Scanner Type 111 (not tested) | | | | |

# Recommendations:

- Some devices are not available for testing, despite this, we recommend the use of Scanner Type 111
- Use the Filter parameter as much as you can. It will be easier to establish the connection between devices.