

Some manufacturers have the proper tools to make the deployment of the devices fast and easy. In this way, we can enable the USB debugging option through the barcodes scanning:

Zebra devices (Android 8.1.0)

(using StageNow)

Enable USB Debugging




Disable USB Debugging



Honeywell devices

(Provisioning mode enabled)

Enable USB Debugging



Disable USB Debugging

