

## Using Bluetooth headsets

The Bluetooth headsets don't work properly on this ET50 device with Android Marshmallow (v6.0-6.1.1), but do work with Android Lollipop versions (v5.0-5.1.1)