

## Tested successfully on:

Other Android versions – <u>No more tested on this version</u>					
Manufacturer	Device	Android Version	Date	Tnx version	Recommended Config
	Notes				
Zebra	ET50	6.0.1	22/11/19	Emulator 1.0.13.500 BT Pairing 7.0.3.562 Barscanner Zebra 3.0.3.524	
	KO. The PIN is required and the Zebra BT Pairing Utility reappears				

## Notes:

• It seems the devices are required to be upgraded to Oreo or Pie OS.

## Configuration:

Follow the instructions detailed in SSI - General Notes