

Latest recommended config:

#### \_tnx\_profile.jcf

```
"BluetoothSPP": {
    "On": true,
    "Filter": "RS5100",
    "PIN": "12345", (or "")
    "UseDeviceMajor": false,
    "UnpairAll": false,
    "DiscoveryOn": false,
    "BarcodeType": "FNC3",
    "ShowUnpairBarcode": false,
    "ScannerType": 111,
    "TerminatorWait": 0,
    "Terminators": ""
},
```

#### \_tnx\_application.jcf

"Bluetooth": {
"OnAtStart": true,
"OffAtExit": false,
<pre>"KeepPairingOnExit": true,</pre>
"KeepPairingOnStartup": true
}

## Tested successfully on:

Android Oreo (8.x)							
Manufacturer	Device	Android Version	Date	Tnx version	Recommended Config		
	Notes						
	EC30	8.1.0	16/04/20	Emulator 1.0.13.514 BT Pairing 7.0.4.505 Vxt Engine 4.2.5.502 Vxt Calibrate 6.1.2.507	"UnpairAll": false, "ScannerType": 111		
Zebra	<ul> <li>Build number 01-23-18.00-OG-U08-STD</li> <li>Scanner automatically reconnected</li> <li>Voice projects <ul> <li>"HeadsetType": 1 (in _vxt_configuration.jcf file)</li> <li>"AudioMode": MODE_NATIVE</li> <li>Headset reconnected successfully</li> </ul> </li> </ul>						



Zebra	EC30	8.1.0	09/03/20	Emulator 1.0.13.510 BT Pairing 7.0.4.504 Vxt Engine 4.2.5.501 Vxt Calibrate 6.1.2.506	"UnpairAll": false, "ScannerType": 111	
	<ul> <li>Build number 01-23-18.00-OG-U08-STD</li> <li>Scanner automatically reconnected</li> <li>Voice projects <ul> <li>"HeadsetType": 2 (in _vxt_configuration.jcf file)</li> <li>Headset reconnected successfully</li> </ul> </li> </ul>					

Android Nougat (7.x) – <u>No more tested on this version</u>							
Manufacturer	Device	Android Version	Date	Tnx version	Config deviation / Notes		

### **Recommendations:**

• Use the Filter parameter as much as you can. It will be easier to establish the connection between devices.

# Scanner Type 111:

- The use of ScannerType: 111 for Zebra devices requires the BT Pairing service at Android Accessibility menu option to be activated. In addition, it is convenient to use UnpairAll: false, to avoid having to scan multiple times to connect the scanner. UnPairAll: true could be more problemathic when you stablish the connection between the device and the scanner.
- Before using the scanner, please, scan the Non-Discoverable and the AutoReconnect barcodes:





